





**NOTE** ATL Composites check each pump as it is packed to ensure it is correctly assembled. It is the responsibility of the end user to check the pumps are working correctly before use. If a faulty pump is found, ATL Composites will be happy to replace it.

ATL Composites accept no responsibility for incorrect mix ratios caused by human error or faulty pumps.

\* Due to pump manufacturing tolerance limitations, the pumps are set up at a 4.7:1 ratio but could vary between 4.5:1 and 5:1. This is the acceptable mix ratio variation range for WEST SYSTEM® epoxy.